## Message Text

LIMITED OFFICIAL USE

PAGE 01 SAN SA 01167 110901Z ACTION SY-05

INFO OCT-01 ARA-10 ISO-00 STE-01 /017 W ------069884 120945Z /20

R 101424Z MAR 78 FM AMEMBASSY SAN SALVADOR TO SECSTATE WASHDC 7295 INFO AMEMBASSY GUATEMALA AMEMBASSY MANAGUA AMEMBASSY PANAMA

LIMITED OFFICIAL USE SAN SALVADOR 1167

STATE FOR SY/OPS/T PANAMA FOR OIC/RTC

E.O. 11652: N/A TAGS: ASEC, ASUP SUBJECT: COM VEHICLE

**REF: SAN SALVADOR 1099** 

- 1. CB TEAM OF ADAMS AND TRAHAN ARRIVED ON SCHEDULE MARCH 5 AND DEAPRTED ON SCHEDULE ON MARCH 6 AT 1715. ALTHOUGH IT APPEARED THAT SOME PROGRESS WAS MADE IN REPAIRING THE CHEVROLET IMPALA COM VEHICLE, BY NO MEANS IS IT ACCEPTABLE FOR USE.
- 2. THE PROBLEM UNTIL NOW, (DEPENDING UPON THE MECHANIC, VARIOUSLY DESCRIBED AS CARBURETOR, FUEL PUMP OR ELECTRICAL) MAY OR MAY NOT HAVE BEEN IDENTIFIED ALTHOUGH IT IS TRUE THAT THE ENGINE OPERATES BETTER. THE CONCLUSION OF THIS TEAM WAS THE THE ELECTRIC FUEL PUMP HAD BEEN WRONGLY MOUNTED NEAR THE ENGINE BLOCK THEREBY OVERHEATING. THIS WAS "SOLVED" BY MOVING THE PUMP TO THE REAR OF THE CAR, A COOLER SPOT; AND BY PUTTING LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 02 SAN SA 01167 110901Z

AN ADDITIONAL GASKET UNDER THE CARBURETOR. THE MECHANIC TOLD US THAT THE ENGINE OVERHEATS BECAUSE THE ENGINE BLOCK HAS A MANIFOLD OF IMPROPER CAPACITY. THIS IS DUE TO THE FACT THAT THE CAR'S ORIGINAL ENGINE WAS REPLACED BY A LARGER CAPACITY 1974 "SHORT BLOCK" BUT THE SMALLER CAPACITY MANIFLD WAS USED. ONE WONDERS

WHY. IT APPEARS THAT OUR MECHANICS ARE CREATING PROBLEMS FASTER THAN OUR ABILITY TO SOLVE THEM. A NEW MANIFOLD MUST NOW BE ORDERED, DELIVERED AND INSTALLED BEFORE IT WILL BE KNOWN WHETHER OR NOT THE CAR WILL OPERATE DEPENDABLY ENOUGH TO BE RELIED UPON FOR SUSTAINED DUTY. THE MECHANIC TEAM ALSO ADVISED THAT THE AIRCONDITIONING SYSTEM IS FAILING AND MUST BE COMPLETELY REPLACED. A SEALED VEHICLE IN SAN SALVADOR'S HEAT AND WITH THE CITY'S PULLUTION LEVEL, MAKES AIR CONDITIONING A NECESSITY AND NOT A MERE COMFORT ITEM.

- 3. ALSO RECENTLY DISCOVERED IS THE FACT THAT THE CAR "BOTTOMS OUT" AT THE SMALLEST BUMP OR HOLE. IT IS BELIEVED THAT THIS IS DUE TO THE CAR'S WEIGHT VERSUS THE SUSPENSION SYSTEM. NEW HEAVY DUTY SHOCKS WERE INSTALLED; BUT THESE APPEAR TO HAVE NO IMPROVING EFFECT.
- 4. FROM THE BEGINNING WE HAVE HAD TROUBLE WITH THE BRAKES. THE BRAKES DO NOT HOLD WELL AND TEND TO "FADE." NOW THE CHEVROLET DEALER TELLS US THAT THE SERVO SYSTEM IS OF TOO LIGHT A CAPACITY FOR THIS 6000 LBS. VEHICLE AND RECOMMENDS REPLACEMENT WITH HEAVIER DUTY EQUIPMENT.

LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 03 SAN SA 01167 110901Z

5. FOLLOWING CB TEAM DEPARTURE THE CAR SAT UN-MOLESTED IN OUR GARAGE OVERNIGHT. THE FOLLOWING MORNING, MARCH 7, WE CHECKED THE VEHICLE AND FOUND:

A. SIGNIFICANT LEAK OF FLUID FROM THE TRANSMISSION;

- B. AN ENGINE OIL LEAK;
- C. A LEAK WHICH APPEARS TO BE FROM THE POWER STEERING; AND
- D. NUMEROUS LEAKS OF GASOLINE FROM
  THE TANK AREA WHICH HAVE COMPLETELY SATURATED
  THE ARMORING OF THE GASOLINE TANK. THIS, OF COURSE,
  MAKES THE VEHICLE A ROLLING "MOLOTOV COCKTAIL"
  AND THE SLIGHEST SPARK FROM A GLANCING STONE
  COULD SET OFF A MAGNIFICENT DISPLAYT OF FIREWORKS, CARRYING THE U.S. AMBASSADOR WITH IT.

6. UR ASSESSMENT AT THIS JUNCTURE IS THAT THIS CAR IS PLAGUED WITH DEFECTS WHICH MAY NOT BE REPAIRABLE AND WHICH ALMOST SURELY WILL REQUIRE CONSTANT SPECIALIZED ATTENTION BECOMING A VERY COSTLY VENTURE.

7. PRIOR TO DEPARTURE THE MECHANIC TEAM ASSURED US THAT THE CHEVROLET IMPALA IS NOW IN BETTER CONDITION THAN THE VEHICLE ON LOAN TO US FROM GUATEMALA. CERTAINLY IT IS TRUE THAT THE GUATEMALA CAR IS IN BAD SHAPE. AMONG OTHER THINGS. THE STEERING IS BAD; THE ENGINE RUNS BADLY AL-THOUGH WE HAVE TRIED TO KEET IT TUNED. WE SUBMIT THAT THIS VEHICLE IS MARGINAL AT BEST. WE UNDER-LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 04 SAN SA 01167 110901Z

STAND THAT THIS VEHICLE IS SCHEDULED TO BE LOANED TO ANOTHER POST. IN OUR VIEW, THERE IS SOME QUESTION WHETHER THIS CAR WOULD MAKE IT OVERLAND TO MANAGUA. INSTEAD, WE RECOMMEND STRONGLY THAT IT ALSO SHOULD BE REPLACED BY A NEW CAR.

8. IN SUMMARY, EMBASSY CONSIDERS THAT THE CHEVROLET IMPALA WILL NEVER PROVE SUITABLE FOR SAN SALVADOR'S REQUIREMENTS AND THREBY URGES DEPARTMENT TO AUTHORIZE AND SHIP SOONEST A NEW COM VEHICLE WHICH WILL GUARANTEE DEPENDABILITY AT ALL TIMES, BUT PARTICULARLY DURING EMERGENCY SITUATIONS.

DEVINE

LIMITED OFFICIAL USE

NNN

## Message Attributes

Automatic Decaptioning: X Capture Date: 01 jan 1994 Channel Indicators: n/a

**Current Classification: UNCLASSIFIED** 

Concepts: n/a Control Number: n/a Copy: SINGLE Draft Date: 10 mar 1978 Decaption Date: 01 jan 1960 Decaption Note: Disposition Action: RELEASED Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW

Disposition Date: 20 Mar 2014 Disposition Event: Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978SANSA01167
Document Source: CORE

**Document Unique ID: 00** 

Drafter: n/a Enclosure: n/a Executive Order: N/A

Errors: N/A **Expiration:** 

Film Number: D780110-0915

Format: TEL

From: SAN SALVADOR Handling Restrictions: n/a

Image Path: ISecure: 1

Legacy Key: link1978/newtext/t19780382/aaaacrjc.tel

Line Count: 150 Litigation Code IDs: Litigation Codes:

Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: dd9dacc9-c288-dd11-92da-001cc4696bcc

Office: ACTION SY

Original Classification: LIMITED OFFICIAL USE Original Handling Restrictions: n/a Original Previous Classification: n/a Original Previous Handling Restrictions: n/a

Page Count: 3
Previous Channel Indicators: n/a

Previous Classification: LIMITED OFFICIAL USE Previous Handling Restrictions: n/a Reference: 78 SAN SALVADOR 1099

Retention: 0

Review Action: RELEASED, APPROVED Review Content Flags:

Review Date: 11 jul 2005 Review Event: Review Exemptions: n/a **Review Media Identifier:** Review Release Date: n/a Review Release Event: n/a **Review Transfer Date:** Review Withdrawn Fields: n/a

SAS ID: 3372100 Secure: OPEN Status: NATIVE Subject: COM VEHICLE TAGS: ASEC, ASUP To: STATE

Type: TE

vdkvgwkey: odbc://SAS/SAS.dbo.SAS\_Docs/dd9dacc9-c288-dd11-92da-001cc4696bcc

Review Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014

Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014